

	Chłonność Vg [cm3]	Ciśnienie znamiono we P [bar]	Ciśnienie maksymal ne P [bar]	Zakres obrotów N [1/min]	Moment jednostko wy [Mn/bar]	Waga M [kg]
SFM-1	12	140	300	V-00	0,2	12,5
SFM-1	22	160	350	10-1600	0,35	17,8
SFM-1	33	160	350	10-1600	0,52	18
SFM-1	44	160	350	5-1600	0,69	19
SFM-1	66	160	350	5-1300	1	19,2
SFM-1	89	140	300	5-1000	1,4	22
SFM-1	110	140	300	5-850	1,8	22,2
SFM-2	85	250	420	5-850	1,3	42
SFM-2	130	200	420	5-650	2	42
SFM-2	165	250	420	5-850	2,6	60
SFM-2	255	200	420	5-650	4	60
SFM-3	250	250	420	5-650	4	78
SFM-3	360	250	420	5-600	5,7	78
SFM-3	455	250	420	5-550	7,2	78
SFM-3	510	250	420	5-500	8,1	78
SFM-4	720	250	420	5-550	11,4	135
SFM-4	910	250	420	5-500	14,5	135
SFM-5	1100	250	420	5-550	17,5	158
SFM-5	1300	250	420	5-500	20,7	158